
5

25X1



23 April 1956

MEMORANDUM TO: MR. BISSELL

SUBJECT : Blow-outs in U-2 Aircraft

- Attached is a tabulation which indicates the blow-outs experienced in U-2 aircraft from the time we started flying them to 31 March this year. This tabulation is fairly self-explanatory and includes the cause of blow-outs if known.
- On Aircraft 1 and 4, number of blow-outs is fairly high probably because these were test aircraft in which blow-outs were induced. It is interesting to note that while the number of blowouts experienced in these two aircraft is fairly high, the rate of blow-suts is approximated by at least two other aircraft.
- This memorandum is furnished for your information only. It does seem, however, to offer a note of alarm in that if the average rate of blow-outs of one in seven is experienced in actual operations, we can expect arithmetically at least one blow-out per week if we fly at our planned rate of eight sorties per week.

25X1

Celonel, USAF Director of Operations

Attachment (1): Tabulation

AMW/acm

Dist.:

Orig. & cy - addressee w/l cy attmt. Cy #3 - Ops subj. file

Cy #4 - Admin chrono

Cy #5 - Ope chrone

2. 整色 1 张 4 C A A